## **Analyses of Wastewater that Contains RV Waste**

| RV Site                            | Sampling Location      | BOD<br>mg/L | Nitrogen<br>mg/L | FOG<br>mg/L | Remarks  |
|------------------------------------|------------------------|-------------|------------------|-------------|--|
| Bernalillo County                  |                        |             |                  |             |  |
| American RV Park <sup>2</sup>      |                        |             | 81-120 TN        |             | 186 RV spaces                                    |
| High Desert RV Park <sup>2</sup>   |                        |             | 41-80 TN         |             | 50-100 RV spaces                                 |
| Route 66 MHP <sup>2</sup>          |                        |             | 21-40 TN         |             | 29 RV spaces                                     |
| Catron County                      |                        |             |                  |             |  |
| Gila Cliff Dwellings <sup>2</sup>  |                        |             | >120 TN          |             |  |
| Dona Ana County                    |                        |             |                  |             |  |
| Las Cruces KOA <sup>2</sup>        |                        | 101-300     | >120 TN          |             | 69 RV spaces                                     |
| Western Skies RV <sup>2</sup>      |                        | 101-300     |                  |             |  |
| Eddy County                        |                        |             |                  |             |  |
| SKP RV Park <sup>2</sup>           |                        |             | >120 TN          |             | 120 RV spaces                                    |
| White's City <sup>2</sup>          |                        |             | 41-80 TN         |             | ·  |
| <u>Lea County</u>                  |                        |             |                  |             |  |
| Finish Line RV Park <sup>3</sup> - | three treatment system | s each cons | sisting of two   | septic ta   | nks in series                                    |
|                                    | West #1                | >560        | 16 NO3           | 41          | 5/18/2009  |
|                                    | West #1                | 38          | 17 TN            |             | 8/25/2009 system had been flooded with tap water |
|                                    | West #1 inlet          | 683         | 4 NO3            | 58          | 4/19/2010  |
|                                    | West #1                | 64          |                  |             | 6/9/2010   |
|                                    | West #1 outlet         |             | 87 TN            |             | 5/18/2011  |
|                                    | Middle #2              | 438         | 18 NO3           | 26          | 5/18/2009  |
|                                    | Middle #2              | 20          | 9 TN             |             | 8/25/2009 system had been flooded with tap water |
|                                    | Middle #2 inlet        | 576         | 6 NO3            | 59          | 4/19/2010  |
|                                    | Middle #2 outlet       | 205         | <0.1 NO3         | 33          | 4/19/2010  |
|                                    |                        |             |                  |             | 6/9/2010   |

|   | Middle #2 outlet East #3 East #3 inlet East #3 outlet East #3 outlet    | 371<br>34<br>696<br>98  | 89 TN<br>14 NO3<br>16 TN<br>3 NO3<br>1 NO3 | 57<br>48<br>52 | 5/18/2011<br>5/18/2009<br>8/25/2009 system had been flooded with tap water<br>4/19/2010<br>4/19/2010<br>6/9/2010<br>5/18/2011 |
|---|---|-------------------------|--|----------------|---|
| Lincoln County  |   |                         |  |                |   |
| Little Creek RV Park <sup>2</sup>   |   |                         | 81-120 TN                                  |                | 65 RV spaces  |
| River Ranch RV Park <sup>2</sup>  |   |                         | 41-80 TN                                   |                | 89 RV spaces  |
| Rio Arriba County   |   |                         |  |                |   |
| Cottonwood RV Park <sup>2</sup>   |   | >300                    | 81-120 TN                                  |                | 37 RV spaces  |
| San Juan County Francisco RV Park <sup>3</sup> - to Navajo Lake State Par | wo septic tank and drainf<br>ST 1 inlet<br>ST 2 inlet<br>k <sup>2</sup> | ïeld syste<br>130<br>12 | ms<br>76 TN<br>10 TN<br>>120 TN            |                | waste from 4 RVs at time of sampling waste from 2 RVs and office at time of sampling  |
| San Miguel County Pendaries RV Park <sup>2</sup>                          |   |                         | 41-80 TN                                   |                | 130 RV spaces   |
| Santa Fe County   |   |                         |  |                |   |
| Rancheros de Santa Fe   |   | 31-100                  | 81-120 TN                                  |                | 37 RV spaces  |
| Santa Fe Skies RV Park  | < <sup>2</sup>  |                         | 81-120 TN                                  |                | 97 RV spaces  |
| Sierra County Cedar Cove 1 1  | CT inlot  | 667                     | AE TKNI                                    | 101            | raw DV wasto with chamical additives  |
|   | ST inlet  | 667                     | 45 TKN                                     | 101            | raw RV waste with chemical additives  |
| Cedar Cove 1 1  | ST outlet   | 161                     | 132 TKN                                    | 16             |   |
| Cedar Cove 2 <sup>1</sup>   | ST inlet  | 2020                    | 154 TKN                                    | 245            | raw RV waste w/ chem; sludge disturbed during sampling  |

| Cedar Cove 2 <sup>1</sup>       | ST outlet       | 35     | 58 TKN   | 11  |                                      |
|---------------------------------|-----------------|--------|----------|-----|--------------------------------------|
| Cedar Cove 4 <sup>1</sup>       | ST inlet        | 211    | 168 TKN  | 109 | long-term campers and Park Models    |
| Cedar Cove 4 <sup>1</sup>       | ST outlet       | 66     | 149 TKN  | 11  | long-term campers and Park Models    |
| D & K Storage <sup>1</sup>      | ST inlet        | 221    | 137 TKN  | 17  | raw RV waste with chemical additives |
| Lakeside RV Park <sup>1</sup>   | offsite manhole | 399    | 78 TKN   | 45  | raw RV waste with chemical additives |
| Monticello RV Park <sup>2</sup> |                 | 31-100 | 41-80 TN |     |                                      |

## **Data Sources:**

<sup>&</sup>lt;sup>1</sup> Bohannan Huston Elephant Butte RV report

<sup>&</sup>lt;sup>2</sup> GWB Discharge Permit files

<sup>&</sup>lt;sup>3</sup> LWP files